

		Done Right Fire Gear Repair New Port Richey, Florida
Item	Item Description	Unit Price
	INSPECTION	
1	Inspect Bunker Gear Coat	\$20.00 / Advance
2	Inspect Bunker Gear Pants	\$20.00 / Advance
3	Inspect Brush Gear	No bid
4	Inspect Jumpsuits	No bid
5	Inspect Helmets	\$15.00
6	Inspect Boots	\$15.00
	WASHES	
7	Regular Wash Bunker Gear	\$15.00
8	Regular Wash Brush Gear	\$8.00
9	Bio Wash Bunker Gear	\$18.00
10	Bio Wash Brush Gear	\$9.00
11	Heavy Duty Wash Bunker Gear	\$18.00
12	Heavy Duty Wash Brush Gear	\$9.00
13	Clean/Polish Boots	\$25.00
14	Clean/Polish Helmets	\$15.00 / Inspect
15	Regular Wash Miscellaneous Items	\$15.00
16	Bio Wash Miscellaneous Items	\$18.00
	REPAIR ITEMS	
17	Replace Suspender button	\$5.00
18	Replace D Ring	\$5.00
19	Replace Grommet	\$2.00
20	Replace or Add Hook	\$5.00
21	Replace or Add MIC Tab	\$5.00
22	Replace Rivet	\$1.00
23	Replace Accessory Strap	\$15.00
24	Replace Strap Handles on Bag	\$5.00
25	Add Postman Buckle/Strap	\$25.00
26	Add Leather Tab	\$5.00
27	Replace Thumb Loop	\$2.00
28	Replace Wristlet	\$25.00
29	Replace Snap	\$5.00
30	Replace Zipper on Bunker Gear	\$35.00
31	Replace Zipper on Bag	\$35.00
32	Replace Zipper on Jumpsuit	\$35.00
33	Sew on Letters or Numbers	\$2.00
34	Make Reflective Letters or Numbers	\$1.00
35	Make and Add New Name Plate	\$26.50
36	Install Pre-Made Name Plate on Coat	\$5.00
37	Move Name Plate	\$5.00
38	Make and Add Name Plate w/Velcro on back	\$31.50
39	Sew on Emblem Patch	\$5.00
40	Install or Replace Flashlight Tab	\$5.00
41	Move Both Knee Pads	\$5.00
42	Re-stitch Seams	\$0.00
43	Sew Our Patch on Coat	\$5.00
44	Patch Gear with Advance Material	\$15.00
45	Patch Gear with Arashield Material	\$15.00
46	Patch Gear with Basofil Material	\$15.00
47	Patch Gear with Black Advance Material	\$15.00
48	Patch Gear with Leather	\$15.00
49	Patch Gear with Nomex Material	\$15.00
50	Patch Gear with PBI Material	\$15.00

51	Patch Pocket with Kevlar Material	\$15.00
52	Patch Gear with Aluminized PBI Material	\$20.00
53	Patch Gear with Ripstop Material	\$15.00
54	Patch Elbow Patch	\$15.00
55	Replace Knee Pad with Arashield	\$30.00
56	Replace Knee Pad with Black Advance	\$30.00
57	Patch Tarp with Cordura Material	\$10.00
58	Replace Scotchlite on Jumpsuit	\$25.00
59	Replace Scotchlite on Entire Coat	\$80.00
60	Replace Scotchlite on Horizontal Strip	\$15.00
61	Replace Scotchlite on Vertical Strip	\$15.00
62	Replace Scotchlite on Arm	\$15.00
63	Replace Scotchlite on Leg	\$15.00
64	Replace Scotchlite on Tail	\$10.00
65	Replace Scotchlite on Pocket	\$10.00
66	Scotchlite Patch	\$15.00
67	Sew Reflective Trim on Jumpsuit	\$25.00
68	Replace Reflexite Strip Around Coat	\$20.00
69	Replace Reflexite on Entire Coat	\$80.00
70	Replace Reflexite Vertical Strip	\$15.00
71	Replace Reflexite on Arm	\$15.00
72	Replace Reflexite on Leg	\$15.00
73	Replace Reflexite on Tail	\$10.00
74	Replace Reflexite on Pocket	\$10.00
75	Triple Trim Patch	\$15.00
76	Replace Velcro on Chin Guard	\$10.00
77	Replace Velcro on Collar	\$15.00
78	Replace One Piece of Velcro on Collar	\$15.00
79	Replace Velcro on Neck	\$10.00
80	Replace Velcro on Flashlight Strap	\$5.00
81	Replace Velcro on Arm Cuff	\$10.00
82	Replace Velcro on Fly	\$15.00
83	Replace Velcro on Hem of Coat	\$5.00
84	Add Velcro to Cuffs of Jumpsuit	\$5.00
85	Replace Velcro Around Knee Pad	\$10.00
86	Replace Velcro on Bellow Pocket	\$8.00
87	Replace Velcro on Radio or Back Pocket	\$4.00
88	Replace Velcro on Storm Flap	\$15.00
89	Replace Velcro on Liner's Fly	\$4.00
90	Replace Velcro on Harness tabs	\$2.00
91	Shorten Liner of Pants	\$25.00
92	Shorten Pants	\$25.00
93	Shorten Pants and Liner	\$50.00
94	Create Rapid Rescue Opening in Coat	\$50.00
95	Rapid Rescue Harness for Above	\$50.00
96	Fabricate 10 Foot Howd Strap	\$15.00
97	Fabricate 6 Foot Howd Strap	\$10.00
98	Fabricate SCBA Tags-Blk Adv w/3Letters or numbers	\$15.00
99	Letter and Numbers for SCBA Tags	\$1.00